




Company : LANXESS Industry: Petrochemical Location: La Wantzenau - France Application : Pillow Block

Lanxess elastomer at La Wantzenau (Strasbourg – 67) produces synthetic elastomer.

They reguraly have pillow block failure on archimede screw conveyor. The leakage from stuffing box is a mixture of elastomer and water + soda. The screw have to be stopped and repaired every 3 - 4 months.

In 2008 MD Distribution proposed the installation of 4 INPRO/SEAL Sphere Align on two equipments.

To date no failure and no stop of the equipment have been observed.






## **TECHNICAL DESCRIPTION:**

Split Pillow Block SKF - SNH 520-617


Inpro/Seal : VBXX-CAP LOC SPHERE ALIGN Ø 90 mm P/N°: 1401-A-42269-0







Anti Rotation Pin Groove



Loctite<sup>®</sup>

